

中低碳鋼成份表

鋼種記號		化 學 成 份 %				
JIS	SAE	C	Si	Mn	P	S
	1006	Max 0.08	0.015~0.035	0.25~0.40	Max 0.030	Max 0.035
	1008	Max 0.10		0.30~0.50		
S10C	1010	0.08~0.13		0.30~0.60		
S15C	1015	0.13~0.18				
S20C	1020	0.18~0.23				
	1021	0.18~0.23		0.60~0.90		
	1022	0.18~0.23		0.70~1.00		
S22C		0.20~0.25		0.30~0.60		
S25C	1025	0.22~0.28				
S30C	1030	0.27~0.33		0.60~0.90		
S35C	1035	0.32~0.38				
S45C	1045	0.42~0.48				
S50C	1050	0.47~0.53				
S55C	1055	0.52~0.58				
	1060	0.55~0.65				